

TCA-200



Electronics at the  
service of Industry



TCA-201  
(KEYPAD)

ENG

ESP

## TCA-200/201 TACHOMETERS

### Instruments range of IED Electronics.

Periodic signals display for different industries and sectors.

TCA200/201 is a periodic signals display. These ones can be generated in automation areas or in engineering processes. It is used to display and / or control frequency, rotation speed, etc.

---

**5-digit visualisation**

---

**Direct signal or external sensor input**

---

**Two signal inputs with filters, up to 1 KHz and 50 KHz**

---

**Two independent relay outputs (relay version)**

## OPERATION

### Visualisation

The display shows a value in a 5-digit format up to 99999 with 2 alarm LED indicators. It has 2 frequency inputs with filters, up to 1 KHz or 50 KHz (depending on the signal amplitude). When the filter value is exceeded, "0" will be displayed. When 99999 is exceeded, "UP-r" will be displayed. Programmable resolution

The visualisation of irregular periodic signals can be stabilised by programming. The integrating factor, which is used to regulate the time the display makes the average of the measurements taken, can be configured in step 22.

The position of the decimal point can be configured without the measurement being affected.

### Functions

It can work with frequency meter (Hz) or rpm direct functions (without programming conversion) or with direct or reverse tachometer functions.

In the direct tachometer mode, when the frequency of the signal increases, the visualization increases, and in the reverse tachometer mode when the frequency increases, the visualization decreases.

### Relays

The versions with relays has 2 independent outputs (alarms). One of them is switched on and the other one is normally open. Their activation / deactivation can be configured in different ways.

## PROGRAMMING

To access the programming buttons, when the version has no external keypad, insert a flat-headed screwdriver into the groove marked as "Open to program" and lever the front cover out.

To enter the "Programming Mode" press simultaneously "ENTER" and "ESCAPE" for 2 seconds.

### KEY FUNCTIONS IN PROGRAM MODE

Button	Function
<b>UP</b>	Increases the program steps (P00, P01...), as well as the options or values to be programmed
<b>DOWN</b>	Decreases the program steps, and the options or values to be programmed
<b>ENTER</b>	Enters the program step which validates options and values and exits the program step.
<b>ESC</b>	Return to the program steps.

## PROGRAM STEPS

<b>P00</b>	(0) Exit program mode without saving data, (1) Exit program mode saving data, (2) Restore factory configuration
<b>P01</b>	Working modes: (1) Direct tachometer, (2) Reverse tachometer, (3) Frequency meter (Hz), (4) Rpm [3]
<b>P02</b>	Decimal point: (1) x.xxxx, (2) xx.xxx, (3) xxx.xx, (4) xxxx.x, (5) xxxx [5]
<b>P03</b>	Resolution: (1) 1, (2) 5, (3) 10 [1]
<b>P04</b>	Value to be displayed (1-99999) [1]
<b>P05</b>	Option 1: Input signal reading Enter in the signal input the frequency corresponding to the value entered in P04. During the reading it will display "CALL" If the reading is correct it will display "OK", if it's not, it will display "UP-r" or "0" depending on whether the frequency is too high or there is no signal.
<b>P06</b>	Option 2: Keypad reference Enter on the keypad the value in hertz corresponding to the value entered in P04 [1]
<b>P07</b>	Relay 1. Polarity. (0) Switch off the relay when activating the alarm, (1) Switch on the relay when activating the alarm [1]
<b>P08</b>	Relay 1. Mode. (0) Disabled, (1) It is activated at a certain value and is deactivated at a lower value, (2) It is deactivated when it goes down to the set value [1]
<b>P09</b>	Relay 1. Deactivation value (if P08=1) (1-99999, equal or lower than P10) [4000]
<b>P10</b>	Relay 1. Activation value (if P08=1) (1-99999, equal or lower than P09) [5000]
<b>P11</b>	Relay 1. Threshold value (if P08=2) (1-99999) [10000]
<b>P12</b>	Relay 1. Activation delay in tenths of seconds (1-1000) [1]
<b>P13</b>	Relay 1. Minimum duration of the pulse" in tenths of seconds (0-1000) [0]
<b>P14</b>	Relay 2. Same as P07 of relay 1. [1]
<b>P15</b>	Relay 2. Same as P08 of relay 1. [1]
<b>P16</b>	Relay 2. Same as P09 of relay 1. [9000]
<b>P17</b>	Relay 2. Same as P10 of relay 1. [10000]
<b>P18</b>	Relay 2. Same as P11 of relay 1. [10000]
<b>P19</b>	Relay 2. Same as P12 of relay 1. [1]
<b>P20</b>	Relay 2. Same as P13 of relay 1. [0]
<b>P21</b>	Refresh configuration for low frequencies <sup>1</sup> Maximum time in tenths of second between pulses before displaying 0. (16-80) [16]
<b>P22</b>	Integrating factor (1-100) [16] (1) it displays immediately, (100) average of the signal entered in the last 6,5 seconds Value to be introduced = value in seconds during which it calculates the average/0.0655
<b>P23</b>	Analog output <sup>2</sup> (0-10 V, 0-20 mA or 4-20mA) (0) Disabled, (1-99999) Full scale for the analogue output [0]

### Notas:

<sup>1</sup> It is necessary to increase this parameter when reading frequencies lower than 1 Hz. If this is not done, it will display 0 between pulse and impulse.

<sup>2</sup> Only models with Analogue output mod. AN-200.

- In bold and between brackets "[x]", the factory settings.

## EXAMPLES OF BASIC PROGRAMMING

To display the speed of a motor in Revolutions Per Minute (RPM) its axis has a collector which provides:

- CASE A. 1 impulse per revolution
- CASE B. 10 impulse per revolution

## ENTER THE PROGRAMMING MODE

Press simultaneously "ENTER" and "ESCAPE" for 2 seconds.

**CASE A:** P01=4, P00=2 (END).

**CASE B:** To configure automatically

Connect the collector to the tachometer in terminal 12, move the axis at 300 r.p.m.

P01=1, P02=5, P03=1, P04=300, P05=press ENTER, P00=2 (END).


**CASE B:** To configure manually

P01=1, P02=5, P03=1, P04=300 P06=50 (300r.p.m. x 10ipv=3000, 3000/60 = 50Hz). P00=2 (END).

**ALARMS:** When it displays 300, Relay 1 is activated and it is deactivated when it goes down below 250.


ENTER PROGRAMMING P07=1, P08=1, P09=250  
P10=300, P00=2 (END).

## P7/P14 (RL1, RL2)=1: Alarm with relay On. Graphic.




**P7/P14 (RL1, RL2)=0: Alarm with relay Off (inverse function).**  
The graphics are the inverse of the previous ones.

## CONNECTION




Connection label.



WARNING: Do not input signals in both inputs at the same time

## DIMENSIONS



## TECHNICAL SPECIFICATIONS

### Electrical features

Power supply	230 Vac <sup>1</sup> 50/60Hz
Power consumption	<3.5 VA
Auxiliary outputs	20 Vdc (8 Vdc by bridging terminals 9-11)
Input impedance	10 kΩ
Input voltage	5...35 Vdc
Input frequency	0.2 Hz a 50 KHz <sup>2</sup>
Minimum pulse width	10 µs
Relay maximum voltage	250 Vac
Relay maximum current	4 A

### Visualisation

Number of digits	5
Digits height	15 mm
Colour	Red
Maximum error	<0.1 %

### General

IP protection	2
Front IP protection	50
Working temperature	0...70°C
Weight	0.350 Kg
Dimensions	48x96x120 mm
EMC	EN 61000-6-2:2001 EN 55022:2001, Class B

<sup>1</sup>By default. By changing the tin bridges under the transformer, it can be power supplied with 115 Vac

<sup>2</sup>Terminal 12, with 5 V, maximum frequency 500 Hz or with 10 V fmax 1 KHz.

Terminal 13, with 5 V, maximum frequency 20 KHz or with 10 V fmax 50 KHz.

## REFERENCES AND ACCESSORIES

### References

0007	TCA-200 TACHOMETER Panel (115/230Vac)
0008-0081	TCA-200R TACHOMETER Panel with Relays (24Vdc NO ISOLATED)
0010	TCA-201R TACHOMETER Panel with Relays and Keypad (115/230Vac)
0010-AN-I	TCA-201R TACHOMETER (115/230Vac)+4-20mA ANALOG OUTPUT

PDF download here:



**IED Electronics Solutions S.L.**  
Pol. Plazaola E 6, 31195 Aizoáin. Navarra (Spain)  
[www.iedelectronics.com](http://www.iedelectronics.com)  
[info@iedelectronics.com](mailto:info@iedelectronics.com)



TCA-200



Electrónica al servicio  
de la industria



TCA-201  
[TECLADO]

# TACÓMETROS TCA-200/201

## Gama Instruments de IED Electronics.

Indicador de señales periódicas para diferentes industrias y sectores.

El TCA200/201 es un indicador de señales periódicas. Éstas pueden ser generadas en áreas de automatización y en procesos de ingeniería. Permite visualizar y/o controlar frecuencia, velocidad de rotación, etc.

**Visualización sobre 5 dígitos**

**Entrada de señal directa o mediante sensor externo**

**Dos entradas de señal con filtros, hasta 1 KHz y 50 KHz**

**Dos salidas independientes de relés (versión con relés)**

ENG ↗

ESP ↗

## PRESTACIONES

### Visualización

El indicador muestra el valor sobre 5 dígitos hasta 99999 con 2 LED indicadores de alarma. Tiene dos entradas de frecuencia con filtros, hasta 1 KHz y hasta 50 KHz (dependiendo de la amplitud de señal). Al superar el valor del filtro se visualizará 0 y si se supera 99999 se visualizará UP--r. Resolución programable.

Se puede estabilizar la visualización de señales periódicas irregulares mediante programación. En el paso 22 se puede configurar el factor de integración mediante el cual se regula el tiempo durante que el visualizador efectúa la media de las medidas que toma.

Se puede configurar la posición de la coma, sin que ésta afecte a la medida.

### Funciones

Puede funcionar con funciones directas (sin programar conversión) de frecuencímetro (Hz) y rpm o con funciones de tacómetro Directo o inverso. En la modalidad de tacómetro directo, al incrementar la frecuencia de la señal, aumenta la visualización y en la modalidad de tacómetro inverso a mayor frecuencia de la señal, disminuye la visualización.

### Relés

Las versiones con relés disponen de 2 salidas independientes (alarmas). Un relé es comutado y el otro normalmente abierto pudiéndose configurar su activación/desactivación de diferentes maneras.

## PROGRAMACIÓN

Si la versión no dispone de teclado externo se debe acceder a los pulsadores levantando la carátula frontal haciendo palanca con un destornillador en la abertura señalada como "open to program".

Para entrar en modo de programación, pulsar simultáneamente "Enter" y "Escape" durante 2 segundos.

## FUNCIONES DE LOS PULSADORES EN MODO PROGRAMACIÓN

### Pulsador Función

<b>UP</b>	Incrementa los pasos de programa (P00,P01..), así como las opciones o valores a programar.
<b>DOWN</b>	Decrementa los pasos de programa, así como las opciones o valores a programar.
<b>ENTER</b>	Entra en el paso de programa donde valida opciones y valores y sale del paso de programa.
<b>ESC</b>	Retorna a los pasos de programa.

## PASOS DEL PROGRAMA

<b>P00</b>	(1) Sale sin grabar los cambios, (2) Sale grabando los cambios, (3) Restaurar configuración de fábrica, (4) Manteniendo enter pulsado durante 10 segundos, guarda cambios como configuración de fábrica
<b>P01</b>	Modos de trabajo: (1) Tacómetro directo, (2) Tacómetro inverso, (3) Frecuencímetro (Hz), (4) Rpm [3]
<b>P02</b>	Comas: (1) x.xxxx, (2) xx.xxx, (3) xxx.xx, (4) xxxx.x, (5) xxxx [5]
<b>P03</b>	Resolución: (1) 1, (2) 5, (3) 10 [1]
<b>P04</b>	Valor a visualizar (1-99999) [1]
<b>P05</b>	Opción 1: Lectura señal de entrada. Introducir por la entrada de señal la frecuencia correspondiente al valor introducido en el P04. Durante la lectura aparecerá "CALL". Si la lectura es correcta aparecerá "OK", si no, aparecerá "UP-r" o "0" dependiendo de si la frecuencia es demasiado alta o no hay señal.
<b>P06</b>	Opción 2: Referencia por teclado. Introducir mediante teclado, el valor en hertzios correspondiente al valor introducido en el P04. [1]
<b>P07</b>	Relé 1. Polaridad. (0) Desactiva relé al activar alarma, (1) Activa relé al activar alarma [1]
<b>P08</b>	Relé 1. Modo. (0) Deshabilitado, (1) Se activa a un valor y se desactiva a uno menor, (2) Se activa al descender al valor programado [1]
<b>P09</b>	Relé 1. Valor desactivación (si P08=1) (1-99999, igual o menor que P10) [4000]
<b>P10</b>	Relé 1. Valor activación (si P08=1) (1-99999, igual o mayor que P09) [5000]
<b>P11</b>	Relé 1. Valor de umbral (si P08=2) (1-99999) [10000]
<b>P12</b>	Relé 1. Retardo de activación en décimas de segundo (1-1000) [1]
<b>P13</b>	Relé 1. Duración mínima del pulso en décimas de segundo (0-1000) [0]
<b>P14</b>	Relé2. Igual que P07 de relé 1. [1]
<b>P15</b>	Relé2. Igual que P08 de relé 1. [1]
<b>P16</b>	Relé2. Igual que P09 de relé 1. [9000]
<b>P17</b>	Relé2. Igual que P10 de relé 1. [10000]
<b>P18</b>	Relé2. Igual que P11 de relé 1. [10000]
<b>P19</b>	Relé2. Igual que P12 de relé 1. [1]
<b>P20</b>	Relé2. Igual que P13 de relé 1. [0]
<b>P21</b>	Configuración del refresco para frecuencias bajas <sup>1</sup> Tiempo máximo en décimas de segundo entre impulsos antes de mostrar 0. (16-80) [16]
<b>P22</b>	Factor de integración (1-100) [16] (1) muestra al instante, (100) realiza la media de la señal introducida en los últimos 6,5 segundos Valor a introducir = valor en segundos durante el que hace la media/0.0655
<b>P23</b>	Salida analógica <sup>2</sup> (0-10 V, 0-20 mA o 4-20mA) (0) Inhabilitada, (1-99999) Fondo de escala para la salida analógica [0]

### Notas:

<sup>1</sup> Es necesario aumentar este parámetro cuando se leen frecuencias inferiores a 1 Hz. De no hacerlo, el visualizador mostrará 0 entre pulso e impulso.

<sup>2</sup> Para equipos que dispongan de tarjeta de salida analógica mod. AN-200.

- Entre corchetes "[x]" figuran los valores preconfigurados de fábrica.

## EJEMPLOS DE PROGRAMACIÓN BÁSICA

Se desea visualizar la velocidad de un motor en Vueltas Por Minuto (RPM) y su eje dispone de un captador que proporciona:

- CASO A: 1 impulso por vuelta (i.p.v.).
- CASO B: 10 i.p.v.

## ENTRADA EN PROGRAMACIÓN

Pulsar " ENTER " y " SCAPE " a la vez durante 2 segundos.

**CASO A:** P01=4, P00=2 (FIN).

**CASO B:** Para calibrar de manera automática.


Conectar el captador al equipo en borna 12, poner el eje a 300r.p.m. P01=1, P02=5, P03=1, P04=300, P05=pulsar ENTER, P00=2 (FIN).

**CASO B:** Para calibrar de manera manual.

P01=1, P02=5, P03=1, P04=300 P06=50 (300r.p.m. x 10ipv=3000, 3000/60 = 50Hz). P00=2 (FIN).



**ALARMAS:** Se desea que cuando el equipo marque 300 se active el RELE 1 y se desactive por debajo de 250. ENTRAR EN PROGRAMACIÓN, P07=1, P08=1, P09=250, P10=300, P00=2 (FIN).

## P7/P14 (RL1, RL2)=1: Alarma a relé activado. Gráficas




**P7/P14 (RL1, RL2)=0: Alarma a en reposo (función inversa).**  
Los gráficos son la inversa de los anteriores.

## CONEXIONADO



ATENCIÓN: No introducir señales en las 2 entradas a la vez.

## DIMENSIONES



## CARACTERÍSTICAS TÉCNICAS

### Características eléctricas

Alimentación	230 Vac <sup>1</sup> 50/60Hz
Potencia consumida	<3.5 VA
Salidas auxiliares	20 Vdc (8 Vdc puenteadas bornas 9-11)
Impedancia entrada	10 kΩ
Rango voltaje de entrada	5...35 Vdc
Rango frecuencia de entrada	0.2 Hz a 50 KHz <sup>2</sup>
Anchura mínima de impulso	10 µs
Tensión máxima contacto Relé	250 Vac
Intensidad máxima contacto Relé	4 A

### Visualización

Número dígitos	5
Altura dígitos	15 mm
Color	Rojo
Error máximo	<0.1 %

### General

Protección IP	20
Protección IP frontis	50
Temperatura de trabajo	0...70°C
Peso	0.350 Kg
Dimensiones	48x96x120 mm
EMC	EN 61000-6-2:2001 EN 55022:2001, Class B

<sup>1</sup>Por defecto. Cambiando puentes de estaño bajo el transformador  
posibilidad de alimentar a 115 Vac.

<sup>2</sup>Borna 12, con amplitud de 5 V, frecuencia máxima 500 Hz o con 10 V fmáx 1 KHz.

Borna 13, con amplitud de 5 V, frecuencia máxima 20 KHz o con 10 V fmáx 50 KHz.

## REFERENCIAS Y ACCESORIOS

### Referencias

0007	TCA-200 TACOMETRO Panel (115/230Vac)
0008-0081	TCA-200R TACOMETRO con Relés (24Vdc SIN AISLAR)
0010	TCA-201R TACOMETRO con Relés y Teclado (115/230Vac)
0010-AN-I	TCA-201R TACOMETRO (115/230Vac)+SALIDA ANALOGICA 4-20mA.

Descargar PDF aquí:



**IED Electronics Solutions S.L.**  
Pol. Plazaola E 6, 31195 Aizoáin. Navarra (Spain)  
[www.iedelectronics.com](http://www.iedelectronics.com)  
[info@iedelectronics.com](mailto:info@iedelectronics.com)

